



Centering Indicator

- Tolerance Markers
- With 3 Off Curved Feelers For External Measurement
- With 3 Off Straight Feelers For Internal Measurement
- With Standard Small Hole Feeler
- Foam Lined Storage Box
- With Inspection Report



Stock Code	Range	Reading	Indicating Error	Shank
4107-003	0-3	0,01	0,02	10

(mm)